

FIELD INSPECTION REPORT

13

Date of Inspection : 11/12/2020

Division : Damapur

District : Patna

Name of the Road : Repair of road

Length (km) : 0.615 km

Scheme/Programme : MAINTENANCE

Internal road from Sibandapur to Sahj

Package No.:

Status of the Project:

Ongoing/Completed/Under Maintenance

Road Id No.:

Work is a case of:

New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

No provision of 5 years maintenance.

11/12/20
(Signature)

NAME: Chaturbhuj Mandal

DESIGNATION: I.E.