


FIELD INSPECTION REPORT

Date of Inspection : 6/12/2020		District: Aurangabad	
Division : Aurangabad		Length (km): 4.20 km	
Name of the Road: M.R. Rd from Tetaria Salaiya Road and 54th Main.			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U ✓
b)	Condition of Surfacing		S/U ✓
c)	Riding Quality		S/U ✓
d)	Road Camber		S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)		(U)
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		


 (Signature)

NAME: Dinesh Prasad Singh