

FIELD INSPECTION REPORT

Date of Inspection: 07-12-2020	District: Banka
Division: Banka-2	Length (km): 3.00 KM
Name of the Road: Bypass of Mahamaya Band to Parsapur village	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BA/BAN/20/0006	Road Id No.: 20703501026
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U Ongoing
b)	Condition of Surfacing	S/U Ongoing
c)	Riding Quality	S/U Ongoing
d)	Road Camber	S/U Ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	Yes/No Ongoing
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	Satisfactory S
Unsatisfactory (U)	

(Signature)
07/12/2020

NAME: RANESH KUMAR

DESIGNATION: JE