

FIELD INSPECTION REPORT

Date of Inspection:
 District:
 Length (km):
 Road ID No:
 NMP-2078 20703502040

Parameters to be checked	Remarks
1. Pavement	
a) Road surface condition	ST
b) Condition of Surfacing	ST
c) Riding Quality	ST
d) Road Camber	ST
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f) Construction joints provided or not (CC Pavement)	Yes/No
g) Condition of Bank slope & embankments if any	Yes/No
2. Cross Drainage	
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c) Condition of railings/slab approach for bridges	S/SRI/U
3. Road Furniture	
a) Whether sign boards/informatory/cautionary Board/km & 200m stakes Pavement road markings are provided and maintained	Yes/No
4. Compliance History	
a) Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
 Date:

NAME: KANESH KUMAR

DESIGNATION: JE