


# FIELD INSPECTION REPORT

Date of Inspection: 14.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 2.00 km
Name of Road : MDR to mabhi		
Scheme / Programme: MAINTENANCE		NEW M / P - 2018
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance <i>ongoing</i>		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance <i>up gradation</i>
Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	-
b)	Condition of Surfacing	-
c)	Riding Quality	-
d)	Road Camber	-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	-
f)	Constraction Joint provided or not(CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	-
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

*Sp. pulated date of Completion is 11.9.2020 but till now BT sentae work not started*


Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

  
 14/12/2020  
 (Signature)

NAME:

DESIGNATION :

  
 Anil Prasad  
 JE