

FIELD INSPECTION REPORT

Date of Inspection : 03/12/20	District: Aurangabad
Division: Aurangabad	Length (km): 2.40 km
Name of the Road: Amba Nabinagar to Suli	
Scheme/Programme: MAINTENANCE	
Package No.: MRN/19-20 Aurangabad/24	Road Id No.: 79730/2/19-20
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Surface condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	NO Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stone Pavement road markings are provided and maintained	Yes/No yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Sunil
03/12/2020
(Signature)