

FIELD INSPECTION REPORT

Date of Inspection : 11-12-20	District: Muzaffarpur
Division : R.W.D. Muz. West	Length (km): 4.0
Name of the Road: Bariyaspur East Chauhan Bartha Village - Falar Village	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Work is in progress S/U
b)	Condition of Surfacing	do S/U
c)	Riding Quality	do S/U
d)	Road Camber	do S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	C.C.P. no provision Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	In Progress Yes/No
2.	Cross Drainage	In Progress
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

In Progress
11-12-20
(Signature)

NAME:

DESIGNATION: