FIELD INSPECTION REPORT

Date of In	nspection: 14/12/2020	District: IGHUL	
Division: Janua Length (km): 1,1019			
Vame of	the Road: LO42 - Amin Ich	airy road to Barryan	pyv
Scheme/F	rogramme: MAINTENANCE		
Package	12 140134-13	Road Id No.: 20804102	122
	the Project: Ongoing/Completed/U		
Work is a case of: New Connectivity/Up gradation/ Maintenance Sl. No. Parameters to be checked.			për das tresta
Sl. No.	Parameters to b	e checked	Remarks
1.	Pavement	The second se	And the factor
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U/
d)	Road Camber		J 8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe	e culverts including its painting	S/SPA/U
b)	Condition of Abutment & Wing walls		S/SRI/U N
c)	Condition of railings/slab/approach for		S/SRI/U N
3.	Road Furniture		Dist ->
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/Nø
4	Compliance Il story	The state of the s	
a)	Status of ATR's & any others	d silvys	m Yes

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	'U^.

land I haden

(Signature)

NAME:

DESIGNATION: