

FIELD INSPECTION REPORT

Date of Inspection:	10-12-2020	District:	Supaul
Division:	Triveniganj	Length (km):	5.035 km
Name of the Road:	MMGSY Pantyali PMGSY road to west Ranjipatti Nahar Bank to Valsakisingan		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Under Maintenance</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S SU
b)	Condition of Surfacing	S SU
c)	Riding Quality	S SU
d)	Road Camber	U SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NO
f)	Contractor joints provided or not (CC Pavement)	yes
g)	Compaction of Bank/slope & raincuts if any	NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	SRI
c)	Condition of railings/slab approach for Bridges	SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME:

Surendra Kumar
SDD RWD
Chlota pur

(Signature):

Surendra
10/12/20