FIELD INSPECTION REPORT

	-	District 14 TILLA
Date of Inspection :	1.12.2020	District: KATIHAR
Division: Bassi	7.71	Length (km): 1.607 Km
Name of the Road: L	.041 Nidhor	sc Kaliyadangi
Scheme/Programme:	MAINTENANCE	PMUSY.
Package No.: BR161		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/	Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SIU
b)	Condition of Surfacing	√8/U
c)	Riding Quality	LS/U
d)	Road Camber	VS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yeskip
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	LS/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating

Satisfactory (S)	1'5"
Satisfactory but requires Improvement (SRI)	2 17
Unsatisfactory (U)	. i

(Signature)

NAME: BHAGIRATH RAM

DESIGNATION: ASSISTAN ENGINEER,