


FIELD INSPECTION REPORT

Date of Inspection : 08.12.2020	District: Kishanganj
Division : KISHANGANJ	Length (km): 3.224 km.
Name of the Road: LRP TO RAMGANG.	
Scheme/Programme: MAINTENANCE	MMGSY.
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U — U.
a)	Road Junction condition	S/U-U
b)	Condition of Surfacing	S/U-S
c)	Riding Quality	S/U-S
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No Yes.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U-U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U-S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U-S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No — NO.
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)  08.12.2020

NAME: SUNIL KR. RANJAN
JE/DIGHALBANK-②