

FIELD INSPECTION REPORT

Date of Inspection : 14/12/2020	District: Nalanda.
Division : Bihar Sharif	Length (km): 0.55012.M.
Name of the Road: NH 82 (Matti Gate) To Shukhdev Narayan Lal Bhadur Sitaran memorial videchalge	
Scheme/Programme: MAINTENANCE	BED COVERAGE & RUTTING BUNYADE
Package No.: NABARD	Road Id No.: Balwapar, Fak path Niranwar.
Status of the Project: Ongoing/Completed/Under Maintenance	Under NABARD.
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	- No -

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
14/12/20

NAME: Mullesh Yadav

DESIGNATION: J. E.