

FIELD INSPECTION REPORT

Date of Inspection : 14/12/2020		District: Nalanda.	
Division : Biharcharif.		Length (km): 0.915 K.M.	
Name of the Road: Asthawan Prachand Arinagar Gram Manorampur Se. Soirwa Gupur			
Scheme/Programme: MAINTENANCE		MNP 21515 Path talu	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
a)	Status of ATR's & any others	- NO-	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 14/12/2020

NAME: Mukesh Yadav

DESIGNATION: I.E.