FIELD INSPECTION REPORT

		(1) 中国的 (1) 中国中国的	然此為於於國際的學術的	Commence of the second	
Date of It	ispection: B	12/2020	Districts my 2affarpur	1.5	
Division: muraffarmer Coeft-2 Length (km): 0.983 Km				1.4.6	
Name of	the Rond: Kas	toa main Road Ras	which pul se Ramder manyline	ghar tak	
Scheme/I	rogramme:	MAINTENANCE	The state of the s		
Package		10 11	Rond Id No.:		
	the Project:	Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
Work is a case of:		Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			. Į į	
c)	Riding Quality			S ru	
<u>d)</u>	Road Camber			~S/U	
c)	Whether free aggregates in	Yes/No			
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
(3	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
۵)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/N				
4.	Compliance History				
(د	Status of ATR's & any others			No	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsailsfactory (U)	

(Signature)

NAME:

DESIGNATION: