

FIELD INSPECTION REPORT

Date of Inspection :	District: <i>West Champaran</i>	
Division : <i>Bagaha-2</i>	Length (km): <i>0.820</i>	
Name of the Road: <i>Laxmipur to Jignali</i>		
Scheme/Programme:	MAINTENANCE	
Package No.: <i>BR-37R-065</i>	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Under maintenance</i>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>Maintenance</i>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<i>S</i>
b)	Condition of Surfacing	<i>S</i>
c)	Riding Quality	<i>S</i>
d)	Road Camber	<i>S</i>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<i>N/A</i>
f)	Contraction Joints provided or not (CC Pavement)	<i>N/A</i>
g)	Compaction of flank/slope & raincuts if any	<i>N/A</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<i>yes</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<i>yes</i>
c)	Condition of railings/slab/approach for Bridges	<i>-</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>yes</i>
4.	Compliance History	
a)	Status of ATR's & any others	<i>NO</i>

Overall Rating :

Satisfactory (S)	<i>S</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Nagendra Kumar
19/11/2023
(Signature)

NAME:

Nagendra Kumar

DESIGNATION:

TE