

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Darbhanga</u>
Division : <u>Darbhanga - 02</u>		Length (km): <u>2.05 KM</u>
Name of the Road: <u>PMGSY Road Tetar Pokhar to paswanpola</u>		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		<u>Ongoing/Completed/Under Maintenance</u> ✓
Work is a case of:		<u>New Connectivity/Up gradation/ Maintenance</u> ✓
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S) ✓	S
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
14/12/2020
S.E

[Signature]
14.12.2020
P.E
(Signature)

NAME:

DESIGNATION: