

FIELD INSPECTION REPORT

Date of Inspection :		District: <i>Darbhanga</i>
Division : <i>Darbhanga - 02</i>		Length (km): <i>1.275</i>
Name of the Road: <i>S.H 75 To Muschari Tola</i>		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		☒ Ongoing/Completed/Under Maintenance
Work is a case of:		☒ New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U✓
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	S/U✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No✓
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U✓
b)	Condition of Abutment & Wing-walls, Slab in RCC culverts	S/SRI/U <i>N/A</i>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <i>N/A</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U) ✓	U

Sd/-
14/12/2020
S-E

Sd/-
14.12.2020
(Signature)

NAME:

DESIGNATION: