FIELD INSPECTION REPORT

Date of Inspection: /	2.12.2000	District: Begusan	
Division: monshoul	Bukhani	Length (km): 0.932	
Name of the Road: Sc		· bur Road to Bhitiyarahi	
Scheme/Programme:	MAINTENANCE		
Package No.: MM (5)	4-80	Road Id No.: 320/08/3008	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	n) Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	<i>-</i> 87U
e)	Whether free from detects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
ſ)	Contraction Joints provided or not (CC Pavement)	≯es/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Unsatisfactory (U)	

(Signature)

NAME: SAIYOFF KUMBR

DESIGNATION: J'E