

FIELD INSPECTION REPORT

Date of Inspection: 14-12-2020		District: GAYA	
Division: Nirmal-Bathani		Length (Km.): 0.701	
Scheme/Programme:		MAINTENANCE	
Package No.: L085 Telbighu to Terka		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1	Pavement	✓ S/U	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ Yes/No	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage	✓ S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture	Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History		
a)	Status of ATR's & any others. NO ATR		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Chhotepal
14-12-2020
J.B