## FIELD INSPECTION REPORT

13412(20	Date of Inspection: 15/12/2020		District : GAYA	
Divison: Neemchak Bathani		Length (Km.: 2.17 KM-		
Scheme/Programme:	MAINTENANCE P	NEE PMGSY (LOS2 Tabowan wazirgant Road)		
Package No.: BR-12R-726		Road Id No.:		
tatus of the Project:	Ongoing/Completed/Und	ler Maintenance		
Vork is a case of:	New Confiectivity/Up gra	adation/Maintenance		
31.	Parameters to be checked			Remarks
lo. 1 Pavement		ar mar de		Months Col
a) Road Junction condition			5	S/U
Condition of Surfacing			S	S/U
c) Riding Quality			5	S/U
i) Road Camber			S	S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of 30 1 20 1			Yes	Yes/No
f) [Contraction Joints provided or not (CC Pavement)			Yes	Yes/No
Compaction of flank/slope & raincuts i	if any	and the second second second second	Yes	Yes/No
Cross Drainage	Zaraka wa 1925 ilianga masa da 1926 ilianga masa da 1926 ilianga masa da 1926 ilianga masa da 1926 ilianga masa Ngjaraka masa da 1926 ilianga masa da 1926 ilianga masa da 1926 ilianga masa da 1926 ilianga masa da 1926 iliang	e de la companya de l	No.	
a) Condition of head walls in Hume pipe culverts including its painting			5	
b) [Condition of Abutment & Wing walls, Slab in RCC culvers			NA.	
Condition of railings/slab/approach for Bridges			44	S/SR
Whether sign boards/informatory/caution	onary Board/km & 200m stone	s/Pavement road markings ar	e provided a	nd Yes
Compliance History			NO AT	FD. T
Status of ATR's & any others.			140 11	

VIJay Kumaz Pandey Assistant Engineer

Unsatisfactory (U)

15/12/2020 AB