FIELD INSPECTION REPORT

Date of Inspection : 9.12.2020		**District:** Nalanda	
Division : Rajgir		**Length (km):** 0.680	
Name of the Road: 2047 to T.01 to Baktmul bigha			
Scheme/Programme:	MAINTENANCE 5th year ODR25		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	**Pavement**	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	**Compliance History**	
a)	Status of ATR's & any others	ATR.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

9.12.2020

(Signature)

NAME: SHIVAPRAKASH GUPTA

DESIGNATION: A.E.

Scanned with CamScanner