

FIELD INSPECTION REPORT

Date of Inspection : 14/12/20 District: Nalanda.

Division : Patna

Length (km): 0.730 km

Name of the Road: Loc 1- Loc 2 to Pakrisara

Scheme/Programme: MAINTENANCE

Package No.: BR 24R 313 Road Id No.:

Status of the Project: Ongoing Completed Under Maintenance

Work is a case of: New Connectivity Up gradation Maintenance Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SR ✓
b)	Condition of Surfacing	SR ✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes ✓
g)	Compaction of Bank slope & talus of m/s	Yes ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SR ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SR ✓
c)	Condition of railings skin approach for Bridges	S SR ✓
3.	Road Furniture	
a)	Whether sign board-informatory cautionary Board km & stones Pavement road markings are provided and maintained	Yes ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SR)

Unsatisfactory (U) U

Satish Kumar

NAME:

[Signature]
(Signature) 14/12/20