

FIELD INSPECTION REPORT

Date of Inspection : 14/12/20 District: Nalanda.
 Division : Rajgir Length (km): 0.550km
 Name of the Road: 1036-Lohi to Niyamat Nagar.
 Scheme/Programme: MAINTENANCE Maintenance.
 Package No.: BR 24R-315 Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition.	SI ✓
b)	Condition of Surface	SI
c)	Riding Quality	SI
d)	Road Camber	SI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes No NA
g)	Contraction of Bank, slope & ditches if any	Yes No
2.	Cross Drainage	No.
a)	Condition of head walls in Flume pipe culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings slab approach for Bridges	S SRI U
3.	Road Furniture	
a)	Whether sign board-informatory cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Sakunt Kumar

NAME:

(Signature) 14/12/20