FIELD INSPECTION REPORT

Date of Inspection : 8	3/14/20	District: Sewan	
Division: maharej guj		Length (km): 1-350 Km	
Name of the Road:	To, to Kham	aire	
Scheme/Programme:	renigen to consequence and a sequence of the s	Additional to the control of the con	
Package No.: BR-34R-419		Road Id No.:	
Status of the Project:	Ongoing Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement B .T	The Residence of the second
a)	Road Junction condition	<u>\$70</u>
b)	Condition of Surfacing	
c)	Riding Quality	US/U
d)	Road Camber	N-87U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts it any	Yes/No
2.	Cross Drainage	
(1)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
(1)	Condition of Abutment & Wing walls, Slab in RCC culverts W/A	S/SRI/U
C1	Condition of railings/slab/approach for Bridges /V/A	S/SRI/U
3.	Road Furniture	Company of the party statement of the company of th
11)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
3)	Status of ATR's & any others	Noang

Overall Rating :

Satisfactory (S)	prompts in househouse profits become virgory. A recover-course
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	The same of the sa

Ram Sagn Das NAME:

DESIGNATION:J.E