

FIELD INSPECTION REPORT

Date of Inspection :	14-12-2020	District:	West Champaran
Division :	Bagaha-2	Length (km):	1.200
Name of the Road:	Malahi to Pakri - tar to/a (VR31)		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37R-560	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Under maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A	
f)	Contraction Joints provided or not (CC Pavement)	N/A	
g)	Compaction of flank/slope & raincuts if any	NO	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

Nagesh Kumar
14/12/20
(Signature)

NAME:

Nagesh Kumar

DESIGNATION:

JE