## FIELD INSPECTION REPORT

te of Ins	pection: 1/3	12 2020	Districts myzaffarput		
vision : y	nuzastarpus	Galt-2	Length (km): 0.2201cm	* * * * * * * * * * * * * * * * * * *	
me of th	e Rond: PW	D rucul pargar	h Chowa se mehadoulit	tale Base	
	8	MAINTENANCE	Rond Id No.:		
ckage N		Onning/Complete	1/Under Maintenance		
ork is a	he l'roject:		Jp gradation/ Maintenance		
Sl. No. Parameters to be checked			Remarks		
1.	Pavement				
a)	Road Junction	S/U			
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
ŋ	Contraction Jo	Yes/No			
g)	Compaction	Yes/No <sup>^</sup>			
2.	Cross Drainage				
2)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
(ء	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History				
2)	Status of ATR's & any others			NO	

Overall Rating

Satisfactory (S)	·
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) 36

NAME:

DESIGNATION: