


FIELD INSPECTION REPORT

Date of Inspection :	12/12/20	District:	SIWAN
Division :	MAHARAJGANJ	Length (km):	0.950 KM
Name of the Road:	To 2 nd St	← H.K.42	← 143rd St
Scheme/Programme:	MAINTENANCE	NABARD	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/V
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/V
d)	Road Camber	S/V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	X/SRI/V
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	X/SRI/V
c)	Condition of railings/slab/approach for Bridges	X/SRI/V
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO


Overall Rating :

Satisfactory (S)	→
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	→

(Signature)  12/12/20
A.E

NAME: Manish Kumar Ojha

DESIGNATION: A.E

 12/12/20
MANISHA KUMAR OJHA
(J.E)