

FIELD INSPECTION REPORT

Date Of Inspection : 13/12/20	District: Siwan	
Division: Mahraiganj	Length(KM) :	
Name Of the Road : To 3 से पिपरा मोजे		
Scheme/Programme :	MAINTENANCE GTSNY	
Package No. : MR-N/19-20Mahraiganj/07	Road Id No. :	
Status Of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/✓
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/✓
d)	Road Camber	S/✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR' s & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME :

DESIGNATION :

AE

(Signature)


13/12/20
MANISH KUMAR OJHA (J.E.)