FIELD INSPECTION REPORT Of Inspection: 13/12/20 District: Siwan Length(KM): Wision: Mahrajganj To3 A RIGGE 11215 Name Of the Road: GITSNZ MAINTENANCE Scheme/Programme: Road Id No.: Package No.: MR-N/19-20Mahrajganj/07 Ongoing/Completed/Under Maintenance Status Of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: Remarks Parameters to be Checked SI. No. **Pavement** 1 S/L Road Junction condition a) S/J Condition of Surfacing b) S/LL **Riding Quality** c) S/JJ Road Camber d) Whether free from defects such as visible cracks, exposed aggregates in Yes/No e) case of CC pavement. Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) **Cross Drainage** 2 S/SRI/LY Condition of head walls in Hume pipe culverts including its painting a) S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts b) S/SRI/U Condition of railings/slab/approach for Bridges c) **Road Furniture** 3 Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained a) **Compliance History** 4 No Status of ATR's & any others a) Overall Rating : Satisfactory (S)

NAME:

DESIGNATION:

AE

(Signature)

SRI

MANISH KUMAR OJHA (J.E.)

Unsatisfactory (U)

Satisfactory but requires Improvement (SRI)