FIELD INSPECTION REPORT

	•		- Darl Longo	
Date of I	nspection : —	1112/20 Di	ength (km): 0.960 km malpuz to Kamalpus	manage of the second se
Division	: B	vaul Le	ength (km): 02 960 kee	2 Tanule
Name of	the Road: -	many school, Kan	nalpuz to kamay	- Cherron
Scheme	Linki withing.		pad Id No.:	
Package	the same of the sa	MMG SY Re Ongoing/Completed/Un	The second secon	
	f the Project:	New Connectivity/Up g	radation/ Maintenance	
Sl. No.	a case of:	Parameters to be	CA. The second s	Remarks
1.	Pavement	1		
a)	Road Junction condition			V8/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			- S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			NO
the state of the s	and the state of t	The state of the s		Anna de la constante de la con

Overall Rating :

Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

11/2/20

46hr 111/12/20

(Signature)