

# FIELD INSPECTION REPORT

|                        |                                            |              |             |
|------------------------|--------------------------------------------|--------------|-------------|
| Date of Inspection :   | 12.12.2020                                 | District:    | NAWADA      |
| Division :             | RAJALI                                     | Length (km): | 0.732 km    |
| Name of the Road:      | L 062 278 017 1903 yf 421 25 GURT          |              |             |
| Scheme/Programme:      | MAINTENANCE (PMGSY)                        |              |             |
| Package No.:           | BR-2SR-618                                 | Road Id No.: | 10502760242 |
| Status of the Project: | Ongoing/Completed/Under Maintenance ✓      |              |             |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |             |

| Sl. No. | Parameters to be checked                                                                                        | Remarks        |
|---------|-----------------------------------------------------------------------------------------------------------------|----------------|
| 1.      | <b>Pavement</b>                                                                                                 |                |
| a)      | Road Junction condition                                                                                         | ✓ S/U          |
| b)      | Condition of Surfacing                                                                                          | ✓ S/U          |
| c)      | Riding Quality                                                                                                  | ✓ S/U          |
| d)      | Road Camber                                                                                                     | ✓ S/U          |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | ✓ Yes/No       |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | ✓ Yes/No       |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | Yes/No         |
| 2.      | <b>Cross Drainage</b>                                                                                           |                |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | ✓ S/SRI/U      |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U        |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U        |
| 3.      | <b>Road Furniture</b>                                                                                           |                |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m<br>Yes/No |
| 4.      | <b>Compliance History</b>                                                                                       |                |
| a)      | Status of ATR's & any others                                                                                    | —              |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | 'S' |
| Satisfactory but requires Improvement (SRI) | —   |
| Unsatisfactory (U)                          | —   |

SUNIT-KUMAR  
JE

20.12.2020  
(Signature)