

# FIELD INSPECTION REPORT

|                        |                                                                         |              |        |
|------------------------|-------------------------------------------------------------------------|--------------|--------|
| Date of Inspection :   | 10-12-2020                                                              | District:    | Supaul |
| Division :             | Triveniganj                                                             | Length (km): | 0.6km  |
| Name of the Road:      | Nilesh Kusiyet to Gadav Tola                                            |              |        |
| Scheme/Programme:      | MAINTENANCE                                                             |              |        |
| Package No.:           |                                                                         | Road Id No.: |        |
| Status of the Project: | Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/> |              |        |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance                              |              |        |

| Sl No. | Parameters to be checked                                                                                             | Remarks                        |
|--------|----------------------------------------------------------------------------------------------------------------------|--------------------------------|
| 1.     | <b>Pavement</b>                                                                                                      |                                |
| a)     | Road Junction condition                                                                                              | S/U                            |
| b)     | Condition of Surfacing                                                                                               | S/U                            |
| c)     | Riding Quality                                                                                                       | S <del>S</del>                 |
| d)     | Road Camber                                                                                                          | U <del>S/U</del>               |
| e)     | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | No <del>Yes/No</del>           |
| f)     | Contraction joints provided or not (CC Pavement)                                                                     | Yes <del>Yes/No</del>          |
| g)     | Compaction of flank/slope & raincuts if any                                                                          | Yes <del>Yes/No</del>          |
| 2.     | <b>Cross Drainage</b>                                                                                                |                                |
| a)     | Condition of head walls in Hume pipe culverts including its painting                                                 | <del>NA</del> <del>SRI</del> U |
| b)     | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | NA <del>SRI</del> U            |
| c)     | Condition of railings/slab approach for Bridges                                                                      | NA <del>SRI</del> U            |
| 3.     | <b>Road Furniture</b>                                                                                                |                                |
| a)     | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | No <del>Yes/No</del>           |
| 4.     | <b>Compliance History</b>                                                                                            |                                |
| a)     | Status of ATR's & any others                                                                                         |                                |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

—

—

U

NAME:

Surendra Kumar  
RWD, S.D.O  
Chhatapur

Surendra Kumar  
(Signature) 10/12/20