

FIELD INSPECTION REPORT

Date of Inspection : 13/12/20	District: Siwan
Division: Mahrajganj	Length(KM) : 0.725 KM
Name Of the Road : T03 से मुस्लिम रोड	
Scheme/Programme :	MAINTENANCE
Package No. : MR-N/19-20Mahrajganj/07	Road Id No. :
Status Of the Project :	Ongoing/Completed/Under Maintenance
Work is a case of :	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME :

DESIGNATION :

AE

(Signature)


13/12/20
MANISH KUMAR OJHA (J.E.)