FIELD INSPECTION REPORT

Date of Inspection :	10. 12. 2020	District:	Sayavi	
Division :	chapra-1	Length (km):	0.50000	4
Name of the Road:	L023 6	Prolding		
Scheme/Programme:	MAINTENANCE	mm	634 (BRICK	3)
Package No.:	-	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			
ŝh No.	Parameters to be checked			Remarks
1 Pavement	AND		10000000000000000000000000000000000000	COLUMN TO LABOR.

Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	ALEXCENS OF
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ?
	Condition of railings/slab/approach for Bridges	S/SRL/U
,	Road Furniture	
A SAME	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	and the same
a) S	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NAME:

DESIGNATION:

20121020 101121020 ATZ

(Signature)