

FIELD INSPECTION REPORT

Date of Inspection: 14-12-2020		District: GAYA
Division: Neeleshak Bathani		Length (Km. : 1.1
Scheme/Programme:		MAINTENANCE
Package No. :	Gaya - Bhampur main Road sagd	Road Id No. :
Status of the Project :	Village to Bani	Ongoing/Completed/Under Maintenance
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1	Payment	✓ S/U
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	✓ S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	HA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3	Road Furniture	✓ Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others. NO ATR	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Chhatrapati
14-12-2020
J.L.