

# FIELD INSPECTION REPORT

|                        |                                            |              |          |
|------------------------|--------------------------------------------|--------------|----------|
| Date of Inspection :   | 11/1/20                                    | District:    | Sivam    |
| Division :             | maharajganj                                | Length (km): | 0.500 km |
| Name of the Road:      | pakki Sadak to Kothua                      |              |          |
| Scheme/Programme:      | MAINTENANCE / CTS only                     |              |          |
| Package No.:           |                                            | Road Id No.: |          |
| Status of the Project: | Ongoing Completed/Under Maintenance        |              |          |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | <b>Pavement</b> <i>pce</i>                                                                                           |            |
| a)      | Road Junction condition                                                                                              | ✓ S/U      |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U      |
| c)      | Riding Quality                                                                                                       | ✓ S/U      |
| d)      | Road Camber                                                                                                          | ✓ S/U      |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓   |
| 2.      | <b>Cross Drainage</b>                                                                                                |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | N/A S/SR/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓ S/SR/U   |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | N/A S/SR/U |
| 3.      | <b>Road Furniture</b>                                                                                                |            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/pavement road markings are provided and maintained | ✓ Yes/No   |
| 4.      | <b>Compliance History</b>                                                                                            |            |
| a)      | Status of ATR's & any others                                                                                         | No any     |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | —   |
| Satisfactory but requires Improvement (SR1) | SRI |
| Unsatisfactory (U)                          | —   |

Ram Sagar Das

NAME:

DESIGNATION:

J-E

*Ramesh*  
(Signature) 10/1/20