

FIELD INSPECTION REPORT

Date of Inspection : 10-12-2020 District: Supaul
 Division : Triveniganj Length (km): 0.300km
 Name of the Road: WB Gidhorpatti to Union Tota GTSNY
 Scheme Programme: MAINTENANCE

Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S SU
b)	Condition of Surfacing	S SU
c)	Riding Quality	S SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No
f)	Contractor joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	No
2.	Cross Drainage	
a)	Condition of head walls in frame pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in R.C.C. culverts	S/SRI
c)	Condition of railings/slab approach for Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/In & Out stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI) **SRI**
 Unsatisfactory (U)

NAME:

Sameendra Kumar
 I.D.O RWD
 Chhapra

Surach
 12/12/20
 (Signature)