FIELD INSPECTION REPORT

Date of Inspection: b	12.2020	District: Namada.	
Division: Rajanli		Length (km): 3.100	
	H31 to Mac	laini (Bahadurpur	.)
Scheme/Programme:	MAINTENANCE		
Package No.: MR-N/19-20 Rasarlj-16		Road Id No.: 15271033064	
Status of the Project:	Ongoing/Completed		going.
Work is a case of:	New Connectivity/L	Jp gradation/ Maintenance	V V
SUNO	Parameters to	be checked	Remarks

SI. No.	Parameters to be checked	Remarks
1.	Pavement	and the same of th
a)	Road Junction condition	s/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	s/sri/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
74.	Compliance History	i, leaved a
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	7
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	NA

(Signature)

NAME: Smilling

DESIGNATION: AE