FIELD INSPECTION REPORT

FIELD INSPECTION REPORT		
,	District: E. Champenan	
Date of Inspection: 1112 10 Length (km): 1.80		
Division	: Micros	
Name of the Road: Bankyanyan 78 presented in the Road: MAINTENANCE		
Scheme/Programmer A complete Road Id No.: 31/85(0)9620		
Package	- I Acell MORE WHILL CHANGE	
Status of	New Connectivity/Up gradation/ Maintenance	Remarks
Work is	Parameters to be checked	Remarks Lock
SI. No.	CONFORM P	A Istanted
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber Whether free from defects such as visible cracks, exposed	Yes/No
e)	aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	s/srl/U
a)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
p) .	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of Abutment & Fridges Condition of Abutment & Wing walls, Slab in RCC culverts	s/sri/u
. c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	n Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200r stones/Pavement road markings are provided and maintained	TOSTIO
4.	Gompliance History	No. of the same of
a)	Status of ATR's & any others	ï

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Notéce issered to contracter

7/12/02 (Signature)

NAME: ASHOC Pal

DESIGNATION: JO/RWD Acerej

Scanned with CamScanner

Scanned by CamScanner