FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District:	SAHARSA	
Division: R.w.D. wo	MK'S DIV. SAHARSA	Length (ki	m): 1·10	
Name of the Road: PA	TORE BAZAR PAG	ZHGACHI	YA HOSPITAL	TO STATEO
Scheme/Programme:	MAINTENANCE			
Package No.:		Road Id No.: 20904308088		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√8/ U
b)	Condition of Surfacing	√S/U
c)	Riding Quality	,\$/U
d)	Road Camber	<i>-8</i> 7U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Xes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	HO HO

Overall Rating

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature) J. E

NAME: Some Eymy

DESIGNATION: Junior Engineer

Scanned by Cam Camera