

FIELD INSPECTION REPORT

Date of Inspection : 13.12.2020		District: East Champaran.	
Division : R.W.D. (w) Dhaka		Length (km):	
Name of the Road: Dhaka - Fulwariy Road to Bahadur Path			
Scheme/Programme: MAINTENANCE			
Package No.: MR-N/17-22/Dhaka-21		Road Id No.: 31708602087	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NOTE: 9/3 Submitted to Department.

13/12/2020
(Signature)
EE

NAME: Shesh Nirmal Hoda.

DESIGNATION: A.E

13/12/2020