

# FIELD INSPECTION REPORT

|                                                                            |                          |
|----------------------------------------------------------------------------|--------------------------|
| Date of Inspection : 03.12.2020                                            | District: Saharsa        |
| Division : Saharsa                                                         | Length (km): 2.52 km     |
| Name of the Road: Repair of Bypass road Sharma chack to Siradey via Kahra. |                          |
| Scheme/Programme: MAINTENANCE                                              |                          |
| Package No.:                                                               | Road Id No.: 20904308090 |
| Status of the Project: Ongoing/Completed/Under Maintenance                 | Under Maintenance ✓      |
| Work is a case of: New Connectivity/Up gradation/ Maintenance              | Maintenance ✓            |

| Sl. No. | Parameters to be checked                                                                                             | Remarks      |
|---------|----------------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | <b>Pavement</b>                                                                                                      |              |
| a)      | Road Junction condition                                                                                              | S ✓          |
| b)      | Condition of Surfacing                                                                                               | S/U ✓        |
| c)      | Riding Quality                                                                                                       | S/U ✓        |
| d)      | Road Camber                                                                                                          | S/U ✓        |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                          | N.A. Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | N.A. Yes/No  |
| g)      | Compaction of flank/slope & rainous if any                                                                           | Yes/No ✓     |
| 2.      | <b>Cross Drainage</b>                                                                                                |              |
| a)      | Condition of head walls in Pucca pipe culverts including its painting                                                | N.A. S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in R.C.C culverts                                                           | N.A. S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | N.A. S/SRI/U |
| 3.      | <b>Road Furniture</b>                                                                                                |              |
| a)      | Whether sign boards/informatory/cautionary Board/1m & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓     |
| 4.      | <b>Compliance History</b>                                                                                            |              |
| a)      | Status of ATR's & any others                                                                                         | NO           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | - |
| Satisfactory but requires Improvement (SRI) | - |
| Unsatisfactory (U)                          | U |

*Handwritten Signature*  
03/12/2020  
(Signature)

NAME: KHALIQUZZAMAN

S.E.