

FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020

District: SAHARSA

Division: SAHARSA

Length (km): 3.50 KM

Name of the Road: Repair of road from Menha to Khadipur

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.: 20904308097

Status of the Project: Ongoing Completed Under Maintenance

Work is a cast of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/V
b)	Condition of Surfacing	S/V
c)	Riding Quality	S/V
d)	Road Camber	S/V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	N.A. Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A. Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A. S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Khaliquzzaman
03/12/2020
(Signature)

NAME:

KHALIQUZZAMAN

DESIGNATION:

S.F.