

FIELD INSPECTION REPORT


Date of Inspection : 13.12.2020		District: East Champaran
Division : R.W.D (W) Dhaka		Length (km): 5.250
Name of the Road: Jhaugram Kundwa chinpur to Sishani via Tetwalia		
Scheme/Programme: MAINTENANCE		
Package No.: PIR.N/19.20/Dhaka-19	Road Id No.: 31708602157	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE:- C/s Submitted to Department.


13/12/2020
(Signature)
ER

NAME: Shesh Murul Hodge.


13/12/2020

DESIGNATION: A.E