

FIELD INSPECTION REPORT

Date of Inspection :	15-12-20	District:	CHHAPRA
Division :	SONEPUR	Length (km):	1.61
Name of the Road:	DARIYAPUR TO HARAUNA		
Scheme/Programme:	MAINTENANCE (New maintenance)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Work Not Started		
Work is a case of:	New Connectivity/Up gradation/ Maintenance Repair -		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement Agreement not done (Work is not started)		
a)	Road Junction condition	S/U	N/A
b)	Condition of Surfacing	S/U	N/A
c)	Riding Quality	S/U	N/A
d)	Road Camber	S/U	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N/A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	N/A
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	N/A

(Signature) 15/12/20

NAME: Ashok Kumar Mishra

DESIGNATION: C.E-1