FIELD INSPECTION REPORT

Date of Inspection: 15-12 - 2020		District: Petra
Division: Bark		Length (km): 1.6 KM
Name of the Road: MH	31 to Gram 1	hackerhuse
Scheme/Programme:	MAINTENANCE	V
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Complete	d/Under Maintenance
Work is a case of:		Up gradation/ Maintenance ~

Sl. No.	Parameters to be checked	Remarks		
1.	Payement			
a)	Road Junction condition	S/U/SR		
b)	Condition of Surfacing	S/U		
c)	Riding Quality	Š/U		
d)	Road Camber	S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Compaction of flank/slope & raincuts if any	Yes/No/s		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No		
4.	Compliance History			
a)	Status of ATR's & any others	-		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SQ1
Unsatisfactory (U)	

Note: - 1. Notice issued to contractor

2. Work not started

3. Deuse bush on Flank.

(Signature)

NAME: Ex. Yogeshwar Pandey

DESIGNATION: CE-2