

# FIELD INSPECTION REPORT

Date of Inspection :	15/12/2020	District:	Samastipur
Division :	Dalsinghsari	Length (km):	0.70
Name of the Road:	NH-103 To Uhalipur Muslim Tola		
Scheme/Programme:	MAINTENANCE	MR New-2018	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance on going		
Work is a case of:	New Connectivity/Up gradation/ Maintenance upgradation		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	- S/U
b)	Condition of Surfacing	- S/U
c)	Riding Quality	- S/U
d)	Road Camber	- S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- Yes/No
f)	Contraction Joints provided or not (CC Pavement)	- Yes/No
g)	Compaction of flank/slope & raincuts if any	- Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	- S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	- S/SRI/U
c)	Condition of railings/slab/approach for Bridges	- S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	- only Main Yes/No Board Recd
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

Stipulated Date of completion is 16/9/2020 but till date surface course have not been started. Action against contractor as per MBD clause have been directed.   
 (Signature) Samir Kumar

NAME: Samir Kumar

DESIGNATION: E.E