

# FIELD INSPECTION REPORT

|                                                               |                                              |
|---------------------------------------------------------------|----------------------------------------------|
| Date of Inspection : 15.12.2020                               | District: NALANDA                            |
| Division : Biharsahib                                         | Length (km): 1.579 Km                        |
| Name of the Road: Ballia Brandi Middle School to Ballia Bigha |                                              |
| Scheme/Programme: MAINTENANCE                                 | New maintenance Policy - 2018                |
| Package No.:                                                  | Road Id No.:                                 |
| Status of the Project:                                        | Ongoing/Completed/Under Maintenance ✓        |
| Work is a case of:                                            | New Connectivity/Up gradation/ Maintenance ✓ |

| Sl. No. | Parameters to be checked                                                                                             | Remarks      |
|---------|----------------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | Pavement                                                                                                             |              |
| a)      | Road Junction condition                                                                                              | ✓ S/U S      |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U S      |
| c)      | Riding Quality                                                                                                       | ✓ S/U S      |
| d)      | Road Camber                                                                                                          | ✓ S/U S      |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No ✓/✓ |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No ✓/✓ |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No ✓/✓ |
| 2.      | Cross Drainage                                                                                                       |              |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U      |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U      |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U      |
| 3.      | Road Furniture                                                                                                       |              |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓/✓ Yes/No   |
| 4.      | Compliance History                                                                                                   |              |
| a)      | Status of ATR's & any others                                                                                         | —            |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U)                          | — |

NAME:

Rana Borun Kumar Singh

DESIGNATION:

Executive Engineer.

(Signature)

15.12.2020