

# FIELD INSPECTION REPORT

|                        |                                             |              |           |
|------------------------|---------------------------------------------|--------------|-----------|
| Date of Inspection :   | 15/12/20                                    | District:    | V AISHALI |
| Division :             | HASIPUR                                     | Length (km): | 7.50 km   |
| Name of the Road:      | Repair of Road from Matariy to 13 archway a |              |           |
| Scheme/Programme:      | MAINTENANCE                                 |              |           |
| Package No.:           |                                             | Road Id No.: |           |
| Status of the Project: | Ongoing/Completed/Under Maintenance         |              |           |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance  |              |           |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                      |          |
| a)      | Road Junction condition                                                                                              | S/U      |
| b)      | Condition of Surfacing                                                                                               | ✓S/U     |
| c)      | Riding Quality                                                                                                       | ✓S/U     |
| d)      | Road Camber                                                                                                          | ✓S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No   |
| 2.      | <b>Cross Drainage</b>                                                                                                |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U  |
| 3.      | <b>Road Furniture</b>                                                                                                |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓ |
| 4.      | <b>Compliance History</b>                                                                                            |          |
| a)      | Status of ATR's & any others                                                                                         |          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) | ✓ |
| Unsatisfactory (U)                          |   |

15/12/2020  
(Signature)

NAME: RATNESH SINGH

DESIGNATION: EE