

(2)

Old M/R (3054)

## FIELD INSPECTION REPORT

|                                                                           |                          |
|---------------------------------------------------------------------------|--------------------------|
| Date of Inspection : 15-12-2020                                           | District: Bhojpur        |
| Division : Ara                                                            | Length (km): 1.100 K.M.  |
| Name of the Road: Ara Salampur path ke ramakpur more to Ramakpur gaon tak |                          |
| Scheme/Programme: MAINTENANCE                                             |                          |
| Package No.:                                                              | Road Id No.: 10401600840 |
| Status of the Project: Ongoing/Completed/Under Maintenance ✓              |                          |
| Work is a case of: New Connectivity/Up gradation/ Maintenance             |                          |

| Sl. No. | Parameters to be checked                                                                                        | Remarks     |
|---------|-----------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | Pavement                                                                                                        |             |
| a)      | Road Junction condition                                                                                         | S/U ✓       |
| b)      | Condition of Surfacing                                                                                          | S/U ✓       |
| c)      | Riding Quality                                                                                                  | S/U ✓       |
| d)      | Road Camber                                                                                                     | S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | Yes/No ✓    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No ✓    |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | Yes/No ✓    |
| 2.      | Cross Drainage                                                                                                  |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U     |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U     |
| 3.      | Road Furniture                                                                                                  |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m Yes/No |
| 4.      | Compliance History                                                                                              |             |
| a)      | Status of ATR's & any others                                                                                    | NO          |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |



(Signature)

NAME: